

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
486	qMp firmware cooker	Error	Tancat	Normal	TP-Link CPE-510-v3 images not generated	Roger Pueyo Centelles	02/27/2021 07:27 PM
485	qMp (Quick Mesh Project) - Packages	Error	Tancat	Baixa	MikroTik devices have their MAC addresses removed	Roger Pueyo Centelles	12/07/2020 06:31 PM
484	qMp (Quick Mesh Project) - Packages	Error	Tancat	Alta	Switched Ethernet devices with all ports in one VLAN are not correctly handled during autoconfiguration	Roger Pueyo Centelles	12/01/2020 07:46 PM
481	qMp (Quick Mesh Project) - Packages	Error	Tancat	Urgent	LAN bridge consistently gets 169.254.185.1 address during qmp_autoconf	Roger Pueyo Centelles	07/07/2020 05:00 PM
479	qMp (Quick Mesh Project) - Packages	Suport	Tancat	Normal	"Country Code" in qMp easy setup not really working	Roger Pueyo Centelles	07/10/2020 08:48 AM
478	qMp (Quick Mesh Project) - Packages	Suport	Tancat	Normal	"Device ID" in qMp easy setup appears before community selection	Roger Pueyo Centelles	07/04/2020 05:29 PM
475	qMp (Quick Mesh Project) - Packages	Error	Tancat	Alta	/usr/lib/luas/luci/dispatcher.lua:756: module 'luci.cbi' not found:	Roger Pueyo Centelles	12/11/2019 11:53 AM
474	qMp (Quick Mesh Project) - Packages	Error	Tancat	Baixa	Custom community names are not included into the hostname	Roger Pueyo Centelles	02/21/2020 03:27 PM
470	qMp (Quick Mesh Project) - Packages	Característica	Tancat	Baixa	Check WiFi status when using 802.11s on DFS-enforced channels	Roger Pueyo Centelles	01/17/2019 10:25 PM
461	qMp (Quick Mesh Project) - Packages	Característica	Tancat	Normal	Allow choosing wireless country	Roger Pueyo Centelles	02/20/2020 08:18 PM
429	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	A wireless device configured as "ignored" by qMp can not be reconfigured again	Roger Pueyo Centelles	07/04/2020 07:05 PM
423	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	Devices with a single Ethernet interface and a swith driving different ports (e.g. eth0=> eth0.1+eth0.2) are not properly managed if the switch is on eth1 instead of eth0 (case of TL-WR841N-v8)	Roger Pueyo Centelles	04/24/2021 10:44 AM
422	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	802.1AD have small MTU value	Roger Pueyo Centelles	05/05/2020 01:12 PM
214	qMp (Quick Mesh Project) - Packages	Característica	Tancat	Normal	Autodetect mesh/lan/wan device	Roger Pueyo Centelles	09/17/2019 01:50 PM