Assumptes

#	Projecte	Tipus d'assumpte	Estat	Prioritat	Tema	Assignat a	Actualitzat
486	qMp firmware cooker	Error	Tancat	Normal	TP-Link CPE-510-v3 images not generated	Roger Pueyo Centelles	27-02-2021 19:27
485	qMp (Quick Mesh Project) - Packages	Error	Tancat	Baixa	MikroTik devices have their MAC addresses removed	Roger Pueyo Centelles	07-12-2020 18:31
484	qMp (Quick Mesh Project) - Packages	Error	Tancat	Alta	Switched Ethernet devices with all ports in one VLAN are not correctly handled during autoconfiguration	Roger Pueyo Centelles	01-12-2020 19:46
481	qMp (Quick Mesh Project) - Packages	Error	Tancat	Urgent	LAN bridge consistently gets 169.254.185.1 address during qmp_autoconf	Roger Pueyo Centelles	07-07-2020 17:00
479	qMp (Quick Mesh Project) - Packages	Suport	Tancat	Normal	"Country Code" in qMp easy setup not really working	Roger Pueyo Centelles	10-07-2020 08:48
478	qMp (Quick Mesh Project) - Packages	Suport	Tancat	Normal	"Device ID" in qMp easy setup appears before community selection	Roger Pueyo Centelles	04-07-2020 17:29
475	qMp (Quick Mesh Project) - Packages	Error	Tancat	Alta	/usr/lib/lua/luci/dispatcher.lua:756: module 'luci.cbi' not found:	Roger Pueyo Centelles	11-12-2019 11:53
474	qMp (Quick Mesh Project) - Packages	Error	Tancat	Baixa	Custom community names are not included into the hostname	Roger Pueyo Centelles	21-02-2020 15:27
470	qMp (Quick Mesh Project) - Packages	Característica	Tancat	Baixa	Check WiFi status when using 802.11s on DFS-enforced channels	Roger Pueyo Centelles	17-01-2019 22:25
461	qMp (Quick Mesh Project) - Packages	Característica	Tancat	Normal	Allow choosing wireless country	Roger Pueyo Centelles	20-02-2020 20:18
429	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	A wireless device configured as "ignored" by qMp can not be reconfigured again	Roger Pueyo Centelles	04-07-2020 19:05
423	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	Devices with a single Ethernet interface and a swith driving different ports (e.g. eth0=> eth0.1+eth0.2) are not properly managed if the switch is on eth1 instead of eth0 (case of TL-WR841N-v8)	Roger Pueyo Centelles	24-04-2021 10:44
422	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	802.1AD have small MTU value	Roger Pueyo Centelles	05-05-2020 13:12
214	qMp (Quick Mesh Project) - Packages	Característica	Tancat	Normal	Autodetect mesh/lan/wan device	Roger Pueyo Centelles	17-09-2019 13:50