

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
489	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	Duplicate bridge br-lan in routers with switched Ethernet interface	Roger Pueyo Centelles	09/21/2021 06:38 PM
490	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	/usr/bin/qmpcontrol: line 197: ubus_network_wireless: not found	Roger Pueyo Centelles	09/19/2021 08:42 PM
491	qMp firmware cooker	Error	Tancat	Alta	Many 8/64 devices use the qmptiny flavour while they could use qmpsmall	Roger Pueyo Centelles	09/29/2021 12:23 PM
492	qMp (Quick Mesh Project) - Packages	Error	Tancat	Normal	qmp_log locks qmpcontrol configure_network when nothing to print		09/20/2021 07:39 PM
493	qMp (Quick Mesh Project) - Packages	Error	Tancat	Alta	Wired devices with MESH role only are not brought up and don't mesh	Roger Pueyo Centelles	09/23/2021 11:59 PM