

## qMp (Quick Mesh Project) - Packages - Error #477

### Cannot configure qmp-wireless in Nanostation XM post 1846G (menu has disappeared)

02/26/2020 04:27 PM - alex martin

<b>Status:</b>	Nou	<b>Start date:</b>	02/26/2020
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Roger Pueyo Centelles	<b>% Done:</b>	0%
<b>Category:</b>	WEB interface	<b>Estimated time:</b>	4.00 hours
<b>Target version:</b>	5.0.0 "Leverage"	<b>Spent time:</b>	0.00 hour
<b>Description</b>			
Hi,			
Menu and pages for configuring wireless options on qMp tab on qMp firmware on versions 4.2.1 and higher (confirmed also 4.2.2) are missing on Ubiquiti Nanostation XW post 1846G HW revision.			
They can be changed via cli editing /etc/config/qmp and changes are applied after a reboot. Is there a quicker way?			
Regards Alex guifi.net Madrid			

#### History

##### #1 - 02/26/2020 05:14 PM - alex martin

The way to set wireless to mixed mode (although not working, see <http://dev.qmp.cat/issues/476>) is by editing /etc/config/qmp and changing in "config wireless" the "option mode" to "'80211s\_adhoc'"

Resulting in:

```
[...]  
config wireless  
option mode '80211s_adhoc'  
[...]
```

Note that even though this option is set, qmp wireless will only work as legacy in this model, so devices running 3.x will not connect to it in any wireless way.

##### #2 - 02/26/2020 05:16 PM - alex martin

Typo: In this model wireless will only work in \* **802.11s** \* mode, dropping ad-hoc mode.

##### #3 - 07/04/2020 05:31 PM - Roger Pueyo Centelles

- Category set to WEB interface
- Assignee set to Roger Pueyo Centelles
- Target version set to 5.0.0 "Leverage"
- Estimated time set to 4.00 h